CASE STUDY
KUHL SOLUTIONS TO CLIENT PROBLEMS

ICE DAM SCIENCE
Studying Heat Loss

KUHL CASE #06

Solving Ice Dams In Minneapolis
Science + Common Sense + Insulation & Ventilation = No Ice Dams

Frost Melt Patterns
At their most fundamental level, ice dams are the result of the interaction of heat loss and snow on your roof. An experienced Kuhl Thermographer can use photos like these in conjunction with infrared imaging to see the weak points in your homes thermal envelope. If you have a moment on the next frosty morning, take a few photos of your roof from a few angles before the sun hits it. Those photos may end up saving you time and money if you are hoping to fix the root cause of ice dams and home heating inefficiencies.



Infrared imaging confirms what Jack Frost already told us.